

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Botany Worsted Mills, Waste Picker House
176 Parker Avenue
Passaic
Passaic County
New Jersey

HABS No. NJ-982-A

HABS
NJ,
16-PASA,
7-A-

Photographer: E. Kenneth Hoffman

October 1989

- NJ-982-A-1 VIEW NORTHEAST, SOUTH FRONT
- NJ-982-A-2 VIEW SOUTHWEST, NORTH FRONT
- NJ-982-A-3 VIEW WEST, EAST FRONT
- NJ-982-A-4 VIEW NORTH, SOUTHEAST CORNER
- NJ-982-A-5 VIEW SOUTH, NORTHWEST CORNER
- NJ-982-A-6 VIEW SOUTH, SHOWING RELATIONSHIP TO NJ-982-B
- NJ-982-A-7 VIEW SOUTHWEST, WINDOW/DOOR DETAILS and METAL
HOPPER
- NJ-982-A-8 INTERIOR, WESTERN PORTION OF BUILDING (1910-18)
SHOWING TRUSS SYSTEM
- NJ-982-A-9 INTERIOR, EASTERN PORTION OF BUILDING (1935-49)
SHOWING TRUSS SYSTEM
- NJ-982-A-10 INTERIOR, LOOKING SOUTH, SHOWING SLIDING METAL
DOOR
- NJ-982-A-11 INTERIOR, WESTERN PORTION OF BUILDING, WINDOW
DETAIL
- NJ-982-A-12 INTERIOR, WESTERN PORTION OF BUILDING, SKYLIGHT